5

ABSTRACT

A method for heating a zone of an elongate tubular article. A heat resistant, heat transmitting and heat dispersive shroud material is applied to the zone and a hot gas source is applied to the outside of the shroud material to cause heat to be transmitted through the shroud material to the zone.